Wood Destroying Insect Inspection Report Notice: Please read important consumer information on page 2.				
Section I. General Information Inspection Company, Address & Phone	Company's Business Lic. No. Date of Inspection 12/7/2017			
Inspection Services Group, LLC	Address of Property Inspected			
54 S Third Street, Suite 1 Oxford, PA 19363	1			
(484) 324-4500				
Inspector's Name, Signature & Certification, Registration, or Lic. #	Structure(s) Inspected			
Branden Brainard NACH	Home, Garage			
Section II. Inspection Findings This report is indicative of the condition of the above identified structure(s) on the date of inspection and is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or defects. Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected:				
A. No visible evidence of wood destroying insects was observed.				
B. Visible evidence of wood destroying insects was observed as follows:				
1. Live insects (description and location):				
✓ 2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and location):				
Shelter tube at rear of home under deck.				
O Visible demand from wood dealth vita in a statute of a fallowy (dealth in a statute of in a)				
3. Visible damage from wood destroying insects was noted as follows (description and location):				
NOTE: This is not a structural damage report. If box B above is checked, it should be understood that some degree of damage, including hidden damage, may be present. If any questions arise regarding damage indicated by this report, it is recommended that the buyer or any interested parties contact a qualified structural				
professional to determine the extent of damage and the need for repairs.				
Yes No V It appears that the structure(s) or a portion thereof may have been previously treated. Visible evidence of possible previous treatment:				
The inspecting company can give no assurances with regard to work done by other companies. The company that performed the treatment should be contacted for information				
on treatment and any warranty or service agreement which may be in place.				
Section III. Recommendations				
No treatment recommended: (Explain if Box B in Section II is checked)				
Recommend treatment for the control of:				
Termites				
Section IV. Obstructions and Inaccessible Areas The inspector may write out obstructions				
The following areas of the structure(s) inspected were obstructed or inaccessible:			or use the following optional key: 1. Fixed ceiling 13. Only visual access	
Basement 1, 3, 4, 5, 8, 9, 24,			2. Suspended ceiling 3. Fixed wall covering 14. Cluttered condition 15. Standing water	
☑ Main Level 1, 3, 4, 6, 8, 9,			Floor covering 16. Dense vegetation S. Insulation 17. Exterior siding Cabinets or shelving 18. Window well covers	
				V Galrage 10 Wood rile
Z Exterior 17 8. Furnishings 20. Now 21 Lineage conditions 21 Lineage conditions 20. Now 21 Lineage conditions 22 Lineage conditions 21 Lineage conditions 22 Lineage condition			8. Furnishings 20. Snow 9. Appliances 21. Unsafe conditions	
10 No access or entry 22. Bigid fram bo			10. No access or entry 22. Rigid foam board	
☐ Other =		11. Limited access 23. Synthetic stucco 12. Noaccessbeneath 24. Duct work, plumbing, and/or wiring		
Section V. Additional Comments and Attachments (these are an integral part of the report)				
Attachments				
Signature of Seller(s) or Owner(s) if refinancing. Seller acknowledges that all information regarding W.D.I. infestation, damage, repair, and treatment history has been disclosed to the buyer.		Signature of Buyer. The undersigned hereby acknowledges receipt of a copy of both page 1 and page 2 of this report and understands the information reported.		
x	l x	×		